

Subject: NOTICE TO MARINERS NO 28 of 2021 - DO NOT REPLY TO THIS EMAIL
Date: Wednesday, 16 June 2021 at 15:10:45 British Summer Time
From: roz@crouchharbour.org.uk
To: Andy Wise
Attachments: New Outer Buoyage 2021.pdf

NOTICE TO MARINERS No 28 of 2021

NAVIGATION

Buoy Changes in Swallowtail and Whitaker Navigation Channels

Mariners are hereby notified of the following alteration to navigation marks in the Swallowtail and Whitaker Channels as of 15th June 2021. Please find attached chart [not to be used for navigation].

Swallowtail Channel

- **Swallowtail No 1 LT Buoy** has been moved to a new position of:
51° 41.400N - 001° 07.500E
Colour, top mark and light characteristic Fl. Y. 5s remain unchanged.
- **Swallowtail No 2 LT Buoy** has been permanently withdrawn from **51°41.184N 001°06.296E**
- **Swallowtail No 3 LT Buoy** in position **51°40.843N 001°04.391E** has been renamed Swallowtail No 2
New light characteristic is Fl. Y. 10s
Colour, shape and top mark remain unchanged.
- **Swallowtail No 4 LT Buoy** in position **51°40.519N 001°03.487E** has been renamed.
Swallowtail No 3
Light characteristic unchanged Fl. (2) Y. 10s
Colour, shape and top mark remain unchanged.

Whitaker Channel

- **Whitaker No 1 LT Buoy** has been moved to a new position of **51°40.530N 001°05.400E**
Shape, colour, top mark and light FL. G. 5. remain unchanged.
- **Whitaker No 2 LT Buoy** has been moved to a new position of **51°40.250N 001°05.400E**
Shape, colour, top mark and light Fl. R. 5s remain unchanged.
- **Whitaker No 3 LT Buoy** has been permanently withdrawn from **51°40.424N 001°04.719E**
- **Whitaker No 4 LT Buoy** has been permanently withdrawn from **51°40.161N 001°04.912E**
- **Whitaker No 5 LT Buoy** in position **51°40.038N 001°03.217E** has been renamed Whitaker No 3 LT Buoy.
New light characteristic is Fl. (2) G. 5s
Shape, colour and top mark remain unchanged.
- **Whitaker No 6 LT Buoy** in position **51°39.757N 001°03.478E** has been renamed Whitaker No 4 LT buoy.
New light characteristic is Fl. (2) R 5s
Shape, colour and top mark remain unchanged.
- **Whitaker No 7 LT Buoy** in position **51°39.540N 001°02.000E** has been renamed Whitaker No 5 LT Buoy.
New light characteristic is Fl. (3) G. 10s
Shape, colour and top mark remain unchanged.
- **Whitaker No 8 LT Buoy** in position **51°39.351N 001°02.000E** has been renamed Whitaker No 6 LT Buoy.
New light characteristic is Fl. (3) R. 10s
Shape, colour and top mark remain unchanged.

Captain Susan Harrison MNM
Harbour Master

16th June 2021

Crouch Harbour Authority, Harbour Office, The Quay, Burnham-on-Crouch, Essex, CM0 8AS
Telephone: 01621 783602. Email: info@crouchharbour.org.uk